

Skywire[®] NL-SW-LTE-TC4NAG LTE CAT 4 PCN, Product Change Notification

NimbeLink Corp

Updated: April 2022



© NimbeLink Corp. 2022. All rights reserved.

NimbeLink Corp. provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use any content contained in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. NimbeLink reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All NimbeLink products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties of merchantability, fitness for a particular purpose and non-infringement.

NimbeLink and Skywire are registered trademarks of NimbeLink Corp. All trademarks, service marks and similar designations referenced in this document are the property of their respective owners.

Table of Contents

Table of Contents	2
1. Introduction	3
2. Migration Overview	3
3. Contact	3
4. Document Version Information	4

1. Introduction

Over their lifetime, Skywire® modems may incur several firmware updates provided by cellular module manufacturers. These updates improve communication, fix bugs, and add features to the module and resulting modem functionality. NimbeLink will stay current with the latest firmware releases. It is recommended that customers also test and apply these new firmware versions when they become available.

The purpose of this PCN is for a Firmware change and to note the supplier adding additional sources for some components on the module. These second source changes do not materially affect the performance of the module and the subsequent NimbeLink modem.

The NL-SW-LTE-TC4NAG is in volume production. The replacement is the NL-SW-LTE-TC4NAG-B, which will transition to volume production in the summer of 2022. NimbeLink recommends you use your supply of NL-SW-LTE-TC4NAG before moving to the new part number. Please contact your supply partner for order placement.

The NL-SW-LTE-TC4NAG Skywire® modem was originally manufactured using Telit firmware version M0F.660006. Telit has since released new firmware, release M0F.660012, which includes many updates including support for AT&T's FirstNet new MTU size requirement. For a complete list of updated items, please refer to Section 2 of Telit's "Delta SW LE910Cx-NF" document (80561DSW10199A rev6.1) available via Telit's Download zone <http://www.telit.com/download-zone/>

For any questions, please contact sales@airgain.com

2. Migration Overview

Customers with existing products can update to version M0F.660012 via a firmware update procedure, example procedure provided in application note 30108 rev 1. <http://nimbelink.com/Documentation/Skywire/4G LTE Cat 3/30235 NL-SW-LTE-TNAG FirmwareUpdateProcedure.pdf>

Customers are not required to migrate to the new Firmware. New designs should migrate to part number NL-SW-LTE-TC4NAG-B which is specific to firmware version M0F.660012 to have the most current version of Firmware for new design starts.

3. Contact

For further information please contact NimbeLink sales team at:

Sales@airgain.com

4. Document Version Information

Revision	Description	Date
1	- Initial document release.	03/29/2022
2	- Fixed formatting errors.	4/15/2022